

www.vaisala.com



CANE SUGAR SYRUP

Typical end products

Sugar and syrup for sweetening soft drinks, beer brewing, preserves, beverage, sweets, liqueurs, ethanol, etc.



Introduction

Evaporation is a crucial step in the sugar making process. The main purpose of the evaporation is to raise the sugar content in the juice to reach the saturated condition required for crystallization.

Evaporation usually takes place in a multiple effect evaporator heated with steam. Evaporators are the largest heat users and major contributors to losses in sugar cane factories. These factors make effective evaporator control crucial to overall factory efficiency.

Application

The *thin syrup* (light-colored syrup) from the extraction plant is evaporated in multiple effect evaporators to concentrate it and to obtain the syrup which is fed to the pan station (crystallization). The dissolved solids concentration is raised from an initial concentration of 10-15 Brix to 50-75 Brix. The concentrated solution is known as *heavy syrup*.

Control of evaporation is crucial for the sugar factories. The main objectives for an evaporator control system are control of Brix and a smooth operation.

An optimally concentrated syrup improves the operation downstream and ensures a high product quality. If the syrup fed to the crystallizers exceed its limit, spontaneous nucleation can happen producing crystals out of specification which require reprocessing and increase the operating costs.

Good evaporation control also allows the evaporators to smooth out process fluctuations and to adjust automatically and immediately to the changes in the syrup flowrate.

Instrumentation and installation

Vaisala Polaris[™] PR53 Process Refractometer is the ideal instrument for controlling sugar factory operations. The refractometer can be installed directly in the process line for continuous monitoring the Brix of the juice and syrup throughout the entire process. The Brix measurement by the refractometer is accurate and reliable and it is not affected by the presence of undissolved particles, crystals or bubbles.

The refractometer is installed in the inlet and outlet of evaporation as well as intermediate evaporation stages. The information given by the refractometer helps to optimize the process and ensure high-quality product for the downstream factory.



www.vaisala.com

SUGAR AND SWEETENERSAPPLICATION NOTE1.02.03CANE SUGAR EVAPORATION

The refractometer provides Ethernet and 4-20 mA output signals that can be used for real-time process control. For example, the refractometer's signal can be used to adjust the feed of syrup to the capacity of the evaporation plant by using a feed-forward control. It is also possible to use the signal to regulate the quantity of heavy syrup added to the feed syrup, thus keeping the feed concentration to the evaporation plant constant.

In the intermediate stages, the refractometer is used in a control loop that keeps the syrup concentration constant by regulating the steam flow, or by regulating the amount of syrup returned to the evaporator. The refractometer also helps to maximize the storage capacity by maintaining automatically the concentrated syrup at a high-level of solids.

In some plants, the heavy syrup contains additives and supersaturated impurities (e.g. oxalic acid), which may crystallize on the prism. Therefore, an automatic steam wash is required. In some extreme cases, it is preferable to mount the refractometer in a narrow by-pass line downstream of a small cooling heatexchanger, where the impurities crystallize. Typical measurement range in this application is 50-80 Brix.

Instrumentation	Description
- T	The Vaisala Polaris PR53GP Process Refractometer is a heavy-duty instrument with non- weld body construction for diverse applications. The optional flange-mounted pipe flow cell installation accessory allows flange-mounted installation in a wide variety of pipe sizes.
User Interface	Vaisala Polaris process refractometers are Indigo compatible. Expand features with Indigo, including data logging, wash control and settings, measurement parameters, diagnostics and service updates.
Prism wash systems	For applications with sticky process conditions the prism wash options are steam wash system, pressure wash system ja water wash system.
Measurement range	Refractive Index (nD) 1.3200 – 1.5300, corresponding to 0-100 Brix.

Ref. B211955EN-B © Vaisala 2023



Soluciones en Instrumentación, Automatización y Control Industrial

www.seita.com.co